



- LEGEND**
- Building Walls
 - Grid Coordinates (1 meter x 1 meter cells)
 - Soil boring location
 - Contamination less than 1 meter on walls
 - Contamination up to 1 meter on walls
 - Surficial floor contamination

Post-Remedial Action Report
Area 4,4A, and 4B

Figure 4.3-1
Summary of Contamination and Remedial Results

Linde Site, Tonawanda, New York